

	Type	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition	Errors	Ref #
1	BRS	45939	(inertia\$1 acceler\$7) near3 (sens\$3 detect\$3 transducer\$1 measur\$6 monitor\$3)	US-PGPUB; USPAT	2004/12/01 11:06				S1
2	BRS	270	piezo\$8 same diaphragm\$1 same mass\$2	US-PGPUB; USPAT	2004/12/01 10:44				S2
3	BRS	70	S1 and S2	US-PGPUB; USPAT	2004/12/01 09:07				S3
4	BRS	26	S1 same S2	US-PGPUB; USPAT	2004/12/01 08:39				S4
5	BRS	957	inertia\$1 near3 accelerometer\$1	US-PGPUB; USPAT	2004/12/01 09:07				S9
6	BRS	70	(S1 S9) and S2	US-PGPUB; USPAT	2004/12/01 09:07				S10
7	BRS	26	(S1 S9) same S2	US-PGPUB; USPAT	2004/12/01 09:07				S11
8	BRS	44	S3 not S4	US-PGPUB; USPAT	2004/12/01 09:39				S12
9	BRS	2805	piezo\$8 near10 diaphragm\$1	US-PGPUB; USPAT	2004/12/01 09:40				S14
10	BRS	252	(S1 S9) and S14	US-PGPUB; USPAT	2004/12/01 09:40				S15
11	BRS	70	(S1 S9) same S14	US-PGPUB; USPAT	2004/12/01 09:41				S16
12	BRS	48	S16 not (S11 S12)	US-PGPUB; USPAT	2004/12/01 09:41				S17
13	BRS	40683	(inertia\$1 acceler\$7) near3 (sens\$3 detect\$3 transducer\$1 measur\$6 monitor\$3)	EPO; JPO; IBM_TDB	2004/12/01 11:14				S18
14	BRS	120	piezo\$8 same diaphragm\$1 same mass\$2	EPO; JPO; IBM_TDB	2004/12/01 11:02				S19
15	BRS	17	S18 and S19	EPO; JPO; IBM_TDB	2004/12/01 10:59				S20

Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors	Ref #
IS&R	7587	(340/541,545.1,546,545.2,545.6-545.9,565-566,568.1-572.9,573.1,539.11,539.12) .CCLS.	US-PGPUB; USPAT	2004/12/01 11:01				S22
BRS	162	\$18 and piezo\$8 and diaphragm\$1	EPO; JPO; DERWENT; IBM_TDB	2004/12/01 11:02				S23
BRS	145	\$23 not \$20	EPO; JPO; DERWENT; IBM_TDB	2004/12/01 11:02				S24
BRS	8	S24 and mass\$2	EPO; JPO; DERWENT; IBM_TDB	2004/12/01 11:03				S25
BRS	40	S24 and weight\$1	EPO; JPO; DERWENT; IBM_TDB	2004/12/01 11:03				S26
BRS	46	S25 S26	EPO; JPO; DERWENT; IBM_TDB	2004/12/01 11:03				S27
BRS	45939	(inertia\$1 acceler\$7) near3 (sens\$3 detect\$3 transducer\$1 measur\$6 monitor\$3)	US-PGPUB; USPAT	2004/12/01 11:06				S28
BRS	269	S22 and S28	US-PGPUB; USPAT	2004/12/01 11:07				S29
BRS	957	inertia\$1 near3 accelerometer\$1	US-PGPUB; USPAT	2004/12/01 11:14				S30
BRS	7	S22 and S30	US-PGPUB; USPAT	2004/12/01 11:15				S31
BRS	2805	piezo\$8 near10 diaphragm\$1	US-PGPUB; USPAT	2004/12/01 11:08				S32
BRS	3	(S29 S31) and S32	US-PGPUB; USPAT	2004/12/01 11:08				S33
BRS	7	(S29 S31) and piezo\$10 and diaphragm\$1	US-PGPUB; USPAT	2004/12/01 11:10				S34
BRS	3817	(inertia\$1 acceler\$7) near3 (sens\$3 detect\$3 transducer\$1 measur\$6 monitor\$3)	USOCR	2004/12/01 11:14				S35

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors	Ref #
31	BRS	220	inertia\$1 near3 accelerometer\$1	USOCR	2004/12/01 11:15				S36
32	BRS	287	piezo\$8 near10 diaphragm\$1	USOCR	2004/12/01 11:15				S37
33	BRS	19	(S35 S36) and S37	USOCR	2004/12/01 11:15				S38

Type	L #	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition	Error rs
1 IS&R	L1	374	(340/546,545.2,545.4,545.5) .CCLS.	US -PGPUB; USPAT	2004/12/01 12:36			
2 IS&R	L2	211	(340/545.2,545.4,545.5) .CCLS.	US -PGPUB; USPAT	2004/12/01 12:20			
3 BRS	L4	13	2 and 3	US -PGPUB; USPAT	2004/12/01 12:41			
4 BRS	L5	2	gyroscop\$2 and 1	US -PGPUB; USPAT	2004/12/01 12:34			
5 BRS	L6	207	(security intru\$4) same (gyroscop\$2 inertia\$1 aceler\$7) same (alarm\$3 alert\$3 warn\$3 notif\$7 siren\$1 buzzer\$1 audibl\$1 audio loudspeaker\$1)	US -PGPUB; USPAT	2004/12/01 12:55			
6 IS&R	L7	2183	(340/546,545.2,545.4,545.5,565,566,545.1 ,541) .CCLS.	US -PGPUB; USPAT	2004/12/01 12:37			
7 BRS	L8	13	6 and 7	US -PGPUB; USPAT	2004/12/01 12:39			
8 IS&R	L9	1680	(340/539.1,539.14) .CCLS.	US -PGPUB; USPAT	2004/12/01 12:39			
9 BRS	L10	123	7 and 9	US -PGPUB; USPAT	2004/12/01 12:53			
10 BRS	L14	68	(security intru\$4) same (kit kits) same (alarm\$3 alert\$3 warn\$3 notif\$7 siren\$1 buzzer\$1 audibl\$1 audio loudspeaker\$1)	US -PGPUB; USPAT	2004/12/01 12:54			
11 BRS	L15	16	14 and (gyroscop\$2 inertias\$1 aceler\$7)	US -PGPUB; USPAT	2004/12/01 13:03			
12 BRS	L19	14116	(kit kits) near3 (parts components elements)	US -PGPUB; USPAT	2004/12/01 13:05			
13 BRS	L20	6	14 and 19	US -PGPUB; USPAT	2004/12/01 13:08			
14 BRS	L21	0	3 and 19	US -PGPUB; USPAT	2004/12/01 13:10			
15 BRS	L22	3	(7 9) and 19	US -PGPUB; USPAT	2004/12/01 13:10			
16 IS&R	L3	176	(340/546) .CCLS.	US -PGPUB; USPAT	2004/12/01 13:15			
17 BRS	L23	26	("5587701") .URPN.	USPAT	2004/12/01 13:18			

Type	L #	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition	Errors
18	BRS	L24	14 1 and video\$7	US -PGPUB; USPAT	2004/12/01 13:37			
19	BRS	L25	23 1 and (video\$7 camera\$1)	US -PGPUB; USPAT	2004/12/01 13:37			
20	BRS	L26	262 9 and (video\$7 camera\$1)	US -PGPUB; USPAT	2004/12/01 13:37			
21	BRS	L27	203 9 and video\$7	US -PGPUB; USPAT	2004/12/01 14:04			
22	BRS	L28	400 distinguish\$3 near3 vibrat\$5	US -PGPUB; USPAT	2004/12/01 14:05			
23	BRS	L29	1783 distinguish\$3 near3 (open opened opening close closed closing displace\$4)	US -PGPUB; USPAT	2004/12/01 14:06			
24	BRS	L30	2 28 same 29	US -PGPUB; USPAT	2004/12/01 14:06			
25	BRS	L31	12137 vibrat\$5 near3 (open opened opening close closed closing displace\$4)	US -PGPUB; USPAT	2004/12/01 14:07			
26	BRS	L32	13 (28 or 29) same 31	US -PGPUB; USPAT	2004/12/01 14:11			
27	IS&R	L33	1680 (340/568.1-568.8,571,570) .CCLS .	US -PGPUB; USPAT	2004/12/01 14:12			
28	BRS	L34	743 33 and (motion\$1 movement\$1 remov\$3) .ab,ti,clm.	US -PGPUB; USPAT	2004/12/01 14:12			
29	BRS	L35	225 33 and ((wireless\$2 transmi\$5) near10 (motion\$1 movement\$1 remov\$3))	US -PGPUB; USPAT	2004/12/01 14:14			
30	BRS	L36	60 35 and vibrat\$5	US -PGPUB; USPAT	2004/12/01 14:15			
31	BRS	L37	1 35 and 28	US -PGPUB; USPAT	2004/12/01 14:14			
32	BRS	L38	25727 (sens\$3 detect\$3 transducer\$1) near3 vibrat\$5	US -PGPUB; USPAT	2004/12/01 14:16			
33	BRS	L39	16 35 and 38	US -PGPUB; USPAT	2004/12/01 14:18			
34	BRS	L40	84 35 and (portab\$5 transportab\$5)	US -PGPUB; USPAT	2004/12/01 14:18			
35	BRS	L41	32 35 and (portab\$5 transportab\$5) .ab,ti,clm.	US -PGPUB; USPAT	2004/12/01 14:31			